

RDE Command







Briefing For: 40mm Industry Day

40 mm TDPs

Review, Clean and 3D

Arthur R. Pizza

Act. APO 40mm HV Production US ARMY ARDEC

apizza@pica.army.mil



Introduction

Objective: To provide an update of the ongoing technical review of the 40mm Technical Data Packages. The technical reviews will include the generation of Detailed Specifications and have a threedimensional feature added to the drawings.

TDPs Affected



- High Velocity (MK19 Mod3 GMG)
 - M385A1 Practice
 - M918 Practice ("Flash-Bang")
 - M430A1 High Explosive Dual Purpose (HEDP)
- Low Velocity (M203/M79)
 - M781 Practice ("Orange Dye")
 - M583A1 White Star Parachute ("Illumination")
 - M433 High Explosive Dual Purpose (HEDP)



OUTLINE



- A. Review the TDP
 - 1. Drawings
 - 2. Specifications (Standardize Testing)
 - 3. Packaging Requirements
- B. Generate DTL Specifications as required.
- c. Generate 3D drawings
- D. Release by ECP
- E. ERR the TDP
- F. Continue to improve by ECP



What This Means



- A better TDP set-up for a Systems type contract.
- Up-to-date Detailed Specifications
- Better understanding and improved visualization through 3d.
- Reduced number of ECPs and RFDs and RFWs.
- Better product



Detailed Specifications

- M433 Consolidated 7 specifications into 1: including Spitiback, M118 Ctg Case, Ctg Case LAP, M118& M195 Plug Base and Cup Powder Charge, Liner and Prj. Metal Parts
- M918 Separate Projectile and Cartridge LAP
- M385 Separate Projectile and Cartridge LAP
- M550 Fuze
- M550 Fuze Escapement
- M583/M661/M662
- M781 Completed; Available via

Website

- M169 Case
- M430A1
- Link



MIL-DTL Major Changes

- Moved all end item requirements to Section 3
- Replaced MIL-STD-105 with MIL-STD- 1916
- Consolidated specifications as much as possible
- New format in accordance with MIL-STD- 961E



STATUS

- All changes have been ECPed
- Awaiting CCB board decision
- Approved ECPs are being ERRed
- Any additional changes will go in under a new ECP



Conclusions

- All TDPs were converted to 3D format
- All Specifications are DTL Specs
- ➢ If there are errors in the TDPs will be changed by ECP process
- Reviews by services and contractors are ongoing. Changes will be made by ECP





Questions

Arthur R. Pizza
(973) 724-6032
apizza@pica.army.mil

Leo D'Ulisse (QA)
(973) 724-5715
dulisse@pica.army.mil



Backup Charts

Examples cont.



- Drawing Methods
 - Ansi-Y14.5?
 - Are the proper symbols used?
 - Are the datum's correct?
 - Are the depiction correct?
- Qualified Source of supply
 - Are there qualified sources?
 - Are they still making the item?
- Distribution Statement
 - ► Is the statement correct?
 - ►Is it missing?





Review the TDP

- Check drawings
 - Hierarchy (WBS)
 - Notes
 - Dimensions and Tolerances
 - Drawing Methods
 - Specifications (Standardize Testing When Possible)
 - Qualified source of supply
 - Distribution Statements



Examples



- Hierarchy
 - ► Is there a COAI drawing?
 - ► Is a DTL Spec. attached to the top drawing?
 - Are the Packaging drawings correct and called out?
- Notes
 - Are they clear and understandable?
 - Do they make sense and are they necessary?
- Dimensions and Tolerances
 - > Are the dimensions correct?
 - Are they called out correctly using the right symbols?
 - Does the tolerances make sense?